

To,


**The Principal**  
DAV Mukhyamantri Public School  
Lalaguda, Block- Bastanar  
Distric-Bastar


Sub:- **For Building Safety Certificate.**  
Ref:- You Refe. Letter No. - 417..... Dated 15-09-2019  
== (::00::) ==

Above you reference letter no. 417..... you need the building safety certificate. Model school/DAV MMPS Lalaguda, Bastanar is Constructed in the year of 2015..... by Our Department. As present its Conditions are As below.

1. R.C.C. inclined roof are in good Condition.
2. Flooring are in good Condition.
3. Toilet are in good Condition.

So Certified the building is safe in all Purpose.

  
Sub Engineer.....  
P.W.D. (B/R) Jagdalpur.

  
for अनुविभागीय अधिकारी  
लोक निर्माण विभाग  
उप संभाग दरभा