



APPENDIX - VIII

**PROFORMA REGARDING SAFE DRINKING WATER AND SANITARY CONDITION
CERTIFICATE.**

No. 249

Date: 19.06.2020

It is certified that an inspection team headed by Ms. Nehha Karanam
Sub-Engineer, P.H.E. Sub-Division, Keshka (Name of Officers
with designation) from P.H.E. Sub-Division Office (Name of
Department/Office) inspected the DAV MUKHYAMANTRI PUBLIC SCHOOL
BADERAJPUR AC HONAWANDI (Name & Address of
the School) on 17/06/2020 and found that the DAV MUKHYAMANTRI PUBLIC
SCHOOL HONAWANDI (Name of school) has safe
drinking water facilities for the students and members of staff of the institution and is maintaining
the hygienic sanitation condition in the school building & the campus as per the norms
prescribed by the Central/State/U.T Govt.

The above valid for a period of 01 (one year).

Signature with Seal : [Signature]
ASSISTANT ENGINEER
P.H.E. SUB-DIVISION, KESHKA.
Name : DISTT-KONDAGAON(C.G.)
Designation : _____

To

The Principal
D.A.V. M.M.P.S, Honawandi
Vishranpura, Dist: Kondagum.
(Name & Address of the Institution)